



TEL: +975 8272760
FAX: +975 8272307
AFTN: VQPRYNYX
E-mail:
bhutanais.doat@gmail.com

ROYAL GOVERNMENT OF BHUTAN
DEPARTMENT OF AIR TRANSPORT
AERONAUTICAL INFORMATION SERVICE
Paro International Airport

AIP SUP
001/2020
Published on
19 NOV 2020

PARO AERODROME (VQPR) - RUBBER DEPOSIT ON RWY

**WIE/2107202300 EXCESSIVE RUBBER DEPOSIT BUILDS UP FROM THE TDZ ON BOTH SIDE OF RWY.
DUE TO UNKNOWN FRICTION COEFFICIENT BREAKING ACTION ON RWY COULD BE SLIPPERY WHEN WET. PILOTS TO EXERCISE CAUTION DURING LANDING ON WET SURFACE CONDITION (NOTAM A0024/20 dated 21/08/20 is hereby superseded)**