AIP BHUTAN

AD 1.5 STATUS OF CERTIFICATION OF AERODROME

Sl. Nr.	Aerodrome Name	ICAO Location Indicator	Certificate Number	Validity of Certificate		Remarks
				From	to	Keinar K5
1	Paro International Airport, Paro	VQPR	BCAA/AGA/17-18/ 006	15/03/2018	Until Revoked, Suspended or Cancelled	

	Name of Aerodrome	Exemption	Exemption granted up to
		1. RESA at RWY 33 does not comply to the requirement set forth in Subsection 14.3 under Section 14 of BANRs 2021	31/12/2025
		2. The extend of RWY Strip toward east of airfield does not comply to the requirement set forth in Subsection 14.3 under Section 14 of BANRs 2021	31/12/2025
1	Paro International Airport (VQPR)	3. Provision of RESA at RWY15 does not comply to the requirement set forth in Bhutan Air Navigation Regulations (BANRs) -14.3	31/12/2020
		4. Parallel taxiway strip slope does not comply to the requirement set forth in Bhutan Air Navigation Regulations (BANRs) -14.3	31/12/2020

INTENTIONALLY LEFT BLANK